

```
2019-02-03 12:35:02.00 - info: host.raspberrypi object change system.adapter.iot.0
2019-02-03 12:34:54.886 - info: host.raspberrypi stopInstance system.adapter.iot.0
2019-02-03 12:34:54.886 - info: host.raspberrypi stopInstance system.adapter.iot.0 killing pid 22750
2019-02-03 12:34:54.942 - info: host.raspberrypi instance system.adapter.iot.0 terminated with code 0 (OK)
2019-02-03 12:34:57.415 - info: host.raspberrypi instance system.adapter.iot.0 started with pid 24225
2019-02-03 12:34:59.516 - info: iot.0 starting. Version 0.3.1 in /opt/iobroker/node_modules/iobroker.iot, node: v8.15.0
2019-02-03 12:34:59.552 - info: iot.0 Connecting with al8wym7vjd122g.iot.eu-west-1.amazonaws.com
2019-02-03 12:35:00.339 - info: host.raspberrypi instance system.adapter.ebus.0 started with pid 24235
2019-02-03 12:35:00.378 - info: host.raspberrypi instance system.adapter.dwd.0 started with pid 24240
2019-02-03 12:35:00.914 - info: host.raspberrypi instance system.adapter.luftdaten.0 started with pid 24253
2019-02-03 12:35:00.961 - info: host.raspberrypi instance system.adapter.tankerkoenig.0 started with pid 24254
2019-02-03 12:35:03.154 - debug: ebus.0 objectDB connected
2019-02-03 12:35:03.304 - debug: ebus.0 statesDB connected
2019-02-03 12:35:03.432 - info: ebus.0 starting. Version 0.5.5 in /opt/iobroker/node_modules/iobroker.ebus, node: v8.15.0
2019-02-03 12:35:03.452 - debug: ebus.0 start with interface ebusr
2019-02-03 12:35:03.453 - debug: ebus.0 init variables
2019-02-03 12:35:03.490 - debug: ebus.0 init common variables
2019-02-03 12:35:03.725 - debug: ebus.0 nothing to poll; skip telnet
2019-02-03 12:35:03.728 - debug: ebus.0 request data from http://192.168.0.1:8889/data
2019-02-03 12:35:04.042 - info: dwd.0 starting. Version 2.4.3 in /opt/iobroker/node_modules/iobroker.dwd, node: v8.15.0
2019-02-03 12:35:04.369 - info: luftdaten.0 starting. Version 0.0.6 in /opt/iobroker/node_modules/iobroker.luftdaten, node: v8.15.0
2019-02-03 12:35:05.072 - warn: iot.0 State hm-rpc.0.OEQ0677764.1.STATE is invalid.
2019-02-03 12:35:05.331 - error: tankerkoenig.0 adapter disabled
2019-02-03 12:35:05.504 - error: host.raspberrypi instance system.adapter.tankerkoenig.0 terminated with code 3 (Adapter disabled or invalid config)
2019-02-03 12:35:05.508 - info: host.raspberrypi instance system.adapter.dwd.0 terminated with code 0 (OK)
2019-02-03 12:35:05.078 - warn: iot.0 State hm-rpc.0.OEQ0677764.2.STATE is invalid.
2019-02-03 12:35:05.082 - warn: iot.0 State hm-rpc.0.OEQ0677764.3.STATE is invalid.
2019-02-03 12:35:05.152 - warn: iot.0 State hm-rpc.0.OEQ0677764.2.STATE is invalid.
2019-02-03 12:35:05.156 - warn: iot.0 State hm-rpc.0.OEQ0677764.3.STATE is invalid.
2019-02-03 12:35:05.243 - warn: iot.0 State hm-rpc.0.BidCoS-RF.10.LEVEL is invalid.
2019-02-03 12:35:05.247 - warn: iot.0 State hm-rpc.0.BidCoS-RF.12.LEVEL is invalid.
2019-02-03 12:35:05.250 - warn: iot.0 State hm-rpc.0.BidCoS-RF.13.LEVEL is invalid.
2019-02-03 12:35:05.253 - warn: iot.0 State hm-rpc.0.BidCoS-RF.14.LEVEL is invalid.
2019-02-03 12:35:05.256 - warn: iot.0 State hm-rpc.0.BidCoS-RF.15.LEVEL is invalid.
2019-02-03 12:35:05.260 - warn: iot.0 State hm-rpc.0.BidCoS-RF.16.LEVEL is invalid.
2019-02-03 12:35:05.264 - warn: iot.0 State hm-rpc.0.BidCoS-RF.17.LEVEL is invalid.
2019-02-03 12:35:05.267 - warn: iot.0 State hm-rpc.0.BidCoS-RF.18.LEVEL is invalid.
2019-02-03 12:35:05.270 - warn: iot.0 State hm-rpc.0.BidCoS-RF.19.LEVEL is invalid.
2019-02-03 12:35:05.274 - warn: iot.0 State hm-rpc.0.BidCoS-RF.2.LEVEL is invalid.
2019-02-03 12:35:05.274 - warn: iot.0 State hm-rpc.0.BidCoS-RF.20.LEVEL is invalid.
2019-02-03 12:35:05.274 - warn: iot.0 State hm-rpc.0.BidCoS-RF.21.LEVEL is invalid.
2019-02-03 12:35:05.275 - warn: iot.0 State hm-rpc.0.BidCoS-RF.22.LEVEL is invalid.
2019-02-03 12:35:05.275 - warn: iot.0 State hm-rpc.0.BidCoS-RF.23.LEVEL is invalid.
2019-02-03 12:35:05.276 - warn: iot.0 State hm-rpc.0.BidCoS-RF.24.LEVEL is invalid.
2019-02-03 12:35:05.276 - warn: iot.0 State hm-rpc.0.BidCoS-RF.25.LEVEL is invalid.
2019-02-03 12:35:05.276 - warn: iot.0 State hm-rpc.0.BidCoS-RF.26.LEVEL is invalid.
2019-02-03 12:35:05.276 - warn: iot.0 State hm-rpc.0.BidCoS-RF.27.LEVEL is invalid.
2019-02-03 12:35:05.277 - warn: iot.0 State hm-rpc.0.BidCoS-RF.28.LEVEL is invalid.
2019-02-03 12:35:05.277 - warn: iot.0 State hm-rpc.0.BidCoS-RF.29.LEVEL is invalid.
2019-02-03 12:35:05.281 - warn: iot.0 State hm-rpc.0.BidCoS-RF.20.LEVEL is invalid.
2019-02-03 12:35:05.285 - warn: iot.0 State hm-rpc.0.BidCoS-RF.21.LEVEL is invalid.
2019-02-03 12:35:05.288 - warn: iot.0 State hm-rpc.0.BidCoS-RF.22.LEVEL is invalid.
2019-02-03 12:35:05.292 - warn: iot.0 State hm-rpc.0.BidCoS-RF.23.LEVEL is invalid.
2019-02-03 12:35:05.295 - warn: iot.0 State hm-rpc.0.BidCoS-RF.24.LEVEL is invalid.
2019-02-03 12:35:05.298 - warn: iot.0 State hm-rpc.0.BidCoS-RF.25.LEVEL is invalid.
2019-02-03 12:35:05.301 - warn: iot.0 State hm-rpc.0.BidCoS-RF.26.LEVEL is invalid.
2019-02-03 12:35:05.304 - warn: iot.0 State hm-rpc.0.BidCoS-RF.27.LEVEL is invalid.
2019-02-03 12:35:05.307 - warn: iot.0 State hm-rpc.0.BidCoS-RF.28.LEVEL is invalid.
2019-02-03 12:35:05.310 - warn: iot.0 State hm-rpc.0.BidCoS-RF.29.LEVEL is invalid.
2019-02-03 12:35:05.314 - warn: iot.0 State hm-rpc.0.BidCoS-RF.3.LEVEL is invalid.
2019-02-03 12:35:05.315 - warn: iot.0 State hm-rpc.0.BidCoS-RF.30.LEVEL is invalid.
2019-02-03 12:35:05.315 - warn: iot.0 State hm-rpc.0.BidCoS-RF.31.LEVEL is invalid.
2019-02-03 12:35:05.315 - warn: iot.0 State hm-rpc.0.BidCoS-RF.32.LEVEL is invalid.
2019-02-03 12:35:05.316 - warn: iot.0 State hm-rpc.0.BidCoS-RF.33.LEVEL is invalid.
2019-02-03 12:35:05.316 - warn: iot.0 State hm-rpc.0.BidCoS-RF.34.LEVEL is invalid.
2019-02-03 12:35:05.316 - warn: iot.0 State hm-rpc.0.BidCoS-RF.35.LEVEL is invalid.
2019-02-03 12:35:05.316 - warn: iot.0 State hm-rpc.0.BidCoS-RF.36.LEVEL is invalid.
2019-02-03 12:35:05.317 - warn: iot.0 State hm-rpc.0.BidCoS-RF.37.LEVEL is invalid.
2019-02-03 12:35:05.317 - warn: iot.0 State hm-rpc.0.BidCoS-RF.38.LEVEL is invalid.
2019-02-03 12:35:05.317 - warn: iot.0 State hm-rpc.0.BidCoS-RF.39.LEVEL is invalid.
2019-02-03 12:35:05.320 - warn: iot.0 State hm-rpc.0.BidCoS-RF.30.LEVEL is invalid.
2019-02-03 12:35:05.323 - warn: iot.0 State hm-rpc.0.BidCoS-RF.31.LEVEL is invalid.
2019-02-03 12:35:05.326 - warn: iot.0 State hm-rpc.0.BidCoS-RF.32.LEVEL is invalid.
2019-02-03 12:35:05.329 - warn: iot.0 State hm-rpc.0.BidCoS-RF.34.LEVEL is invalid.
2019-02-03 12:35:05.512 - warn: iot.0 State hm-rpc.0.BidCoS-RF.35.LEVEL is invalid.
2019-02-03 12:35:05.513 - warn: iot.0 State hm-rpc.0.BidCoS-RF.36.LEVEL is invalid.
2019-02-03 12:35:05.515 - warn: iot.0 State hm-rpc.0.BidCoS-RF.37.LEVEL is invalid.
2019-02-03 12:35:05.517 - warn: iot.0 State hm-rpc.0.BidCoS-RF.38.LEVEL is invalid.
2019-02-03 12:35:05.519 - warn: iot.0 State hm-rpc.0.BidCoS-RF.39.LEVEL is invalid.
2019-02-03 12:35:05.523 - warn: iot.0 State hm-rpc.0.BidCoS-RF.4.LEVEL is invalid.
2019-02-03 12:35:05.524 - warn: iot.0 State hm-rpc.0.BidCoS-RF.40.LEVEL is invalid.
2019-02-03 12:35:05.524 - warn: iot.0 State hm-rpc.0.BidCoS-RF.41.LEVEL is invalid.
201
```