

2023-08-03 07:11:51.042 - **info:** admin.0 (1400) ==> Connected system.user.admin from ::ffff:192.168.178.60

2023-08-03 07:11:59.334 - **info:** javascript.0 (3686) Start javascript script.js.HUAWEI_V3

2023-08-03 07:11:59.367 - **info:** javascript.0 (3686) script.js.HUAWEI_V3: Init connection to: 192.168.178.66:502

2023-08-03 07:11:59.404 - **info:** javascript.0 (3686) script.js.HUAWEI_V3: registered 0 subscriptions, 1 schedule, 0 messages, 0 logs and 0 file subscriptions

2023-08-03 07:11:59.423 - **info:** javascript.0 (3686) script.js.HUAWEI_V3: Connected

2023-08-03 07:12:08.124 - **info:** admin.0 (1400) <== Disconnect system.user.admin from ::ffff:192.168.178.60 javascript

2023-08-03 07:12:24.382 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 38200 from id: 1 with error: Slave device busy (retry request again later)

2023-08-03 07:12:39.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 30000 from id: 1 with error: undefined

2023-08-03 07:12:44.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37800 from id: 1 with error: undefined

2023-08-03 07:12:49.387 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 38300 from id: 1 with error: undefined

2023-08-03 07:12:54.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 38400 from id: 1 with error: undefined

2023-08-03 07:12:59.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 47081 from id: 1 with error: undefined

2023-08-03 07:13:04.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 32000 from id: 1 with error: undefined

2023-08-03 07:13:09.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37000 from id: 1 with error: undefined

2023-08-03 07:13:14.381 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37100 from id: 1 with error: undefined

2023-08-03 07:13:19.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37700 from id: 1 with error: undefined

2023-08-03 07:13:24.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 38200 from id: 1 with error: undefined

2023-08-03 07:13:29.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 32000 from id: 1 with error: undefined

2023-08-03 07:13:34.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37000 from id: 1 with error: undefined

2023-08-03 07:13:39.385 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37100 from id: 1 with error: undefined

2023-08-03 07:13:39.827 - **info:** admin.0 (1400) ==> Connected system.user.admin from ::ffff:192.168.178.60

2023-08-03 07:13:44.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37700 from id: 1 with error: undefined

2023-08-03 07:13:49.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 38200 from id: 1 with error: undefined

2023-08-03 07:13:54.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 32000 from id: 1 with error: undefined

2023-08-03 07:13:59.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37000 from id: 1 with error: undefined

2023-08-03 07:14:04.380 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37100 from id: 1 with error: undefined

2023-08-03 07:14:09.373 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37700 from id: 1 with error: undefined

2023-08-03 07:14:13.799 - **info:** admin.0 (1400) <== Disconnect system.user.admin from ::ffff:192.168.178.60 javascript

2023-08-03 07:14:14.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 38200 from id: 1 with error: undefined

2023-08-03 07:14:19.373 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 32000 from id: 1 with error: undefined

2023-08-03 07:14:24.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37000 from id: 1 with error: undefined

2023-08-03 07:14:29.383 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37100 from id: 1 with error: undefined

2023-08-03 07:14:34.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37700 from id: 1 with error: undefined

2023-08-03 07:14:39.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 38200 from id: 1 with error: undefined

2023-08-03 07:14:39.380 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37000 from id: 1 with error: Slave device busy (retry request again later)

2023-08-03 07:14:44.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 32000 from id: 1 with error: undefined

2023-08-03 07:14:54.371 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37100 from id: 1 with error: undefined

2023-08-03 07:14:59.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 37700 from id: 1 with error: undefined

2023-08-03 07:15:04.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 38200 from id: 1 with error: undefined

2023-08-03 07:15:09.372 - **warn:** javascript.0 (3686) script.js.HUAWEI_V3: Error received reading address 32000 from id: 1 with error: undefined

